
#### **INSTRUCTION MANUAL**

## Model No. LS810

**Product Name: Stick-on Count Up Timer** 

### **Main Features**


- Maximum Capacity:
  9999 days
- Adhesive backing sticks to almost any surface
- Automatically LCD screen proper switching format: mm:ss → hh:mm → dd:hh → dddd



## The Keys


S1 – "Start/stop", to start or stop counting S2 – "RESET", to reset reading to zero

## **Symbols**



" $\Delta$ " – flashing means the timer is at counting mode; steady displayed means it is at stop mode.

# **Automatically LCD Screen Proper Switching Formats** in Different Counting Stages





## How to Operate the Timer

- Press S1 to start counting up
- Press S1 again to stop counting
- Press S2 to erase the reading to 00M00S
- Press S1 again to start counting up from 00M00S

## **How to Replace Battery**


This timer is powered with a piece of LR44 or equivalent. Please follow the steps below to replace battery:





to open back cover here

- position of the arrow shown on the above picture, and open the back cover.
- 2. Use the same screw driver to push battery out of the metal holder as the drawing shown below.



- 3. Discard the old battery.
- 4. Insert a fresh battery (positive side up) into the metal holder.
- 5. At the meantime, full LCD blinking and alarm goes off for 3 seconds, then display  $0000_D$ .
- 6. Restore the back cover. Be sure the mark "Made in Taiwan" is at the lower position.

Printed in Taiwan